


Powłelenie styków wyzwolenia Q1	Powłelenie styków wyzwolenia Q2	Powłelenie styków wyzwolenia Q3	Powłelenie styków wyzwolenia Q4
------------------------------------	------------------------------------	------------------------------------	------------------------------------

/9.6 LG



/10.6 N

/7.4	121	122	/6.4	121	122	/9.4	121	122	/8.4	121	122
/10.1	2	10	/10.2	2	10	/10.2	2	10	/10.3	2	10
/13.3	7	11	/13.3	7	11	/13.3	7	11	/13.4	7	11